Picklist Print October 18, 2010 7:40:42	AM			·		Page 1
Work Order ID: 63011						3
		1447 JEDN 12115 AZII (1866).AZIII ESEAS ARK 1866).				
Work Order ID 63	011	_				Page 2
Work Order ID 63 October 18, 2010 7:41:00 A	M					Page 1
Item ID: D3980-041 Revision ID: PRELIM Item Name: Bearpaw Asso	embly	10.10.18		Se	etup Start Stop	
Start Date: 10/18/10 Required Date: 10/18/10 Reference:	Start Qty: 2.00 Req'd Qty: 2.00	1221	Cust Item ID: Customer:			
Approvals: Process Pla	Date:	CDC (WD)	Date:	Rı	un Start Stop	
Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID Tool # Plan Code	Accept Qty		Reject Insp. Number Stamp
	vision Nbr TRENA		_ · · · - 			
100 HandThermo Hand Finishing Thermoforming	Pick KIt Memo Pick Kit	0.00				Bololis.
	Assembly	0.00			,	~ 3
HandThermo Hand Finishing Thermoforming	Memo 1 - Use wearbar to transfer drill ho 2 Deburr 3 - Assemble as per Dwg D3980	0.00 le and open to finish size as per dv	vg		Pi	10/10/18.
<u> </u>	4-Install wearplates as per dwg.		((1"	
	QC2- Inspect parts off machine FAI/FAIB	0.00				
QC Quality Control	Memo	0.00				Ididis

Picklist Print October 18, 2010 7:40:58 AM									Page 2
Work Order ID: 63011									
Parent Item: D3980-041 Parent Item Name: Bearpaw Assembly			18 1888 HINA 1818 1810 BBN 4881 BBN 1811 BBN 111				Start Date: 1 Start Qty: 2		Required Date: 10/18/10 Required Qty: 2.00
D3980-1 429 Bearpaw	Manufactured	No	B & 30/0.	100	Each	0.0000		2	BBJS
D4015-041 Wearbar Weldment	Manufactured	No		100	Each	56.0000	7 	14	33010/18
			<u>Location</u> ST109	L	56 45	Loc Code		3	-
D4211-043 Wearplate, Aft	Manufactured	No	B62514 x	J 100	II Each	0.0000	1	2	333
MS21043-3	Purchased	No		100	Each	2,532.00	0 7	14	10 loles
			Location	<u>I</u>	oc Qty	Loc Code			12/10/18
			FG		76				- -
			103691		76				-
			ST301 11138 <u>3</u> _		2456 23				-
			112314		2433			14	-
(*** - ****			Commercial contractions of the contraction of the c				Company of the second		

• •								
Picklist Print October 18, 2010 7:40:58 AM				····				Page 3
Work Order ID: 63011 Parent Item: D3980-041 Parent Item Name: Bearpaw Assem	bly		HAR 1911 FRIN 1914 FRI 1911 Har 1914 ista 1914 Fri 1914 Fri 1914 Fri		- · · · 	Start Date: : Start Qty: 2		Required Date: 10/18/10 Required Qty: 2.00
MS21043-4	Purchased	No		100	Each	667.0000 4	8	B
			Location	<u>L</u> (oc Qty	Loc Code		191910
			FG		40			-
			104603		40			_
			ST301		627			_
			112492 113069		25			-
			113009		8 294		8'	-
			114784		300			-
NAS1149D0463J 	Purchased	No		100	Each	1,285.000 4	8	33
77 431101			Location	Lo	oe Qty	Loc Code		10/10/18
			ST298	_	1285	<u> </u>		
								_


ST298 1285


10096 10


114576 68

115622 446

115647 761








Dart Aerospace Ltd


W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
10.10.18	ho	WEAR BARS ARE COCATED PER TEMPLATE									

Part No:		PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed	l:	Date:

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	Verification Section C	Approval Chief Eng	Approval QC inspector					
DATE STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date								
10.10.18	110	WEARDARS LOCATED @ 14.0" INSTEAD OF 14.9" AND 1.0" INSTEAD OF 10". R.C.: MEASULEMENTS TRANSFORMS INCOMPETTY FROM DING TO JIG +	10.10.le	ACCEPTABLE DEVIATION. PRAVILY SHOULD HE LEVISED ACCCUMULA.	ioliola		10.10.18	101019				
		VICE VELSA,										

NOTE: Date & initial all entries





E

